

# Centrerpatroner

Str.	D1	D2	D3	H	HI	h	z-d	Max rpm.
80mm	56	67	16	66,5	50	4	3-M6	4000
100mm	70	83	22	74,4	55	3	3-M8	3500
125mm	95	108	30	84,5	58	4	3-M8	3000
160mm	125	140	45	94	65	5	6-M10	2500
200mm	160	176	65	109	75	5	6-M10	2000
250mm	200	224	80	120	80	5	6-M12	1600
315mm	260	286	100	156,5	90	6	6-M16	1200
400mm	330	362	130	173,5	100	6	6-M16	1000
500mm	420	458	210	205	115	6	6-M16	800

